



[www.ototest.net](http://www.ototest.net)

**GÜNCEL TÜRKÇE OBD II ARIZA KODLARI  
TEKNİK BİLGİLER  
ARIZA TESPİT CİHAZLARI**

**HYUNDAİ**

P1100 Manifold Absolute Pressure (MAP) Sensor Malfunction (Open/Short)  
P1102 Manifold Absolute Pressure (MAP) Sensor Malfunction - Low Voltage  
P1103 Manifold Absolute Pressure (MAP) Sensor Malfunction - High Voltage  
P1147 ETS Sub Accel Position Sensor 1 Malfunction  
P1151 ETS Main Accel Position Sensor 2 Malfunction  
P1155 ETS Limp Home Valve  
P1159 Variable Intake Motor Malfunction  
P1171 Electronic Throttle System Open  
P1172 Electronic Throttle System Motor Current  
P1173 Electronic Throttle System Rationality Malfunction  
P1174 Electronic Throttle System #1 Close Malfunction  
P1175 Electronic Throttle System #2 Close Malfunction  
P1176 ETS Motor Open/Short #1  
P1176 ETS Motor Open/Short #2  
P1178 ETS Motor Battery Voltage Open  
P1330 Spark Timing Adjust Malfunction  
P1521 Power Steering Switch Malfunction  
P1607 Electronic Throttle System Communication Error  
P1614 Electronic Throttle System Module Malfunction  
P1632 Traction Control System Malfunction