



[www.ototest.net](http://www.ototest.net)

**GÜNCEL TÜRKÇE OBD II ARIZA KODLARI  
TEKNİK BİLGİLER  
ARIZA TESPİT CİHAZLARI**

**LAND ROVER**

P1137 Land Rover HO2S Failed To Switch To Rich, Bank "A"  
P1138 Land Rover HO2S Failed To Switch To Lean, Bank "A"  
P1157 Land Rover HO2S Failed To Switch To Rich, Bank "B"  
P1158 Land Rover HO2S Failed To Switch To Lean, Bank "B"  
P1171 Land Rover System Too lean, Bank A & Bank B  
P1172 Land Rover System Too Rich, Bank A & Bank B  
P1176 Land Rover FMFR Correction At Maximum Positive Value  
P1177 Land Rover FMFR Correction At maximum Negative Value  
P1178 Land Rover AMFR Correction At Maximum Positive Value  
P1179 Land Rover AMFR Correction At Maximum Negative Value  
P1185 Land Rover HO2S Heater Circuit Open, Upstream Sensors  
P1186 Land Rover HO2S Heater Short Circuit, Upstream Sensors  
P1187 Land Rover HO2S Heater Short Circuit, Upstream Sensors  
P1188 Land Rover HO2S Heater Circuit High Resistance, Upstream Sensors  
P1189 Land Rover HO2S heater Circuit Type 1 Low Resistance, Upstream  
P1190 Land Rover HO2S heater Circuit Type 2 Low Resistance, Upstream  
P1191 Land Rover HO2S Heater Circuit Open, Downstream Sensors  
P1192 Land Rover HO2S Heater Short Circuit, Downstream Sensors  
P1193 Land Rover HO2S Heater Circuit Inferred Open Circuit, Downstream Sensors  
P1194 Land Rover HO2S Heater Circuit High Resistance, Downstream Sensors  
P1195 Land Rover HO2S Heater Circuit Type 1 Low Resistance, Downstream  
P1196 Land Rover HO2S heater Circuit Type 2 Low Resistance, Downstream  
P1199 Land Rover Fuel Level Sensor Circuit Fault  
P1201 Land Rover Injector Open Circuit Or Ground Short, Cylinder 1  
P1202 Land Rover Injector Open Circuit Or Ground Short, Cylinder 2  
P1208 Land Rover Injector Open Circuit Or Ground Short, Cyl. 8  
P1230 Land Rover Fuel Pump Relay Open  
P1231 Land Rover Fuel Pump Relay Short Circuit To Battery Supply  
P1232 Land Rover Fuel Pump Relay Short Circuit To Ground  
P1313 Land Rover Misfire Likely To Damage Catalyst, Bank A  
P1314 Land Rover Misfire Likely To Damage Catalyst, Bank B  
P1315 Land Rover Persistent Misfire  
P1316 Land Rover Misfire Causing Excessive Emissions  
P1317 Land Rover ABS Rough Road Line Low Fault Detected  
P1318 Land Rover ABS Rough Road Line High Fault Detected  
P1361 Land Rover No Ignition Coil Activation, Coil 1  
P1362 Land Rover No Ignition Coil Activation, Coil 2  
P1363 Land Rover No Ignition Coil Activation, Coil 3  
P1364 Land Rover No Ignition Coil Activation, Coil 4  
P1371 Land Rover Early Ignition Coil Activation, Coil 1  
P1372 Land Rover Early Ignition Coil Activation, Coil 2  
P1373 Land Rover Early Ignition Coil Activation, Coil 3  
P1374 Land Rover Early Ignition Coil Activation, Coil 4  
P1440 Land Rover EVAP Purge Valve Stuck Open

P1447 Land Rover Purge Canister Closure Valve Poor Performance  
P1496 Land Rover EVAP system gross leak detected  
P1508 Land Rover IAC Motor Circuit Open  
P1509 Land Rover IAC Motor Circuit Short  
P1514 Land Rover Neutral Drive Load Fault L  
P1516 Land Rover Neutral Drive Gear Change Fault  
P1517 Land Rover Neutral Drive Cranking Fault  
P1550 Land Rover IACV Circuit  
P1607 Land Rover MIL Circuit Short  
P1621 Land Rover Communications With Security ECM Not Within Expected Time  
P1622 Land Rover More Than One Wrong Security Code Received By ECM  
P1701 Land Rover Transfer Box Line Fault  
P1703 Land Rover Transfer Box Line Open Circuit Short Fault  
P1708 Land Rover Transfer Bow Line Short Circuit Fault  
P1775 Land Rover Gearbox Fault  
P1776 Land Rover Gearbox Ignition Retard Request Duration Fault  
P1777 Land Rover Gearbox Ignition Retard Request Line Fault